



OceanMaster Rust Remover

Description

A phosphoric acid-based metal pre-treatment for removing light rust prior to the application of the chosen anti-corrosive paint system. Also suitable for removing oxidation from copper and other metals.

Direction for use

Used diluted with fresh water – 1 volume Rust Remover to 2 volumes of fresh water. Apply to surface by desired method. Allow to foam for 5 to 10 minutes and wash away with copious amount of fresh water.

On oily areas and areas with carbon deposits from welding, some mild surface agitation should be employed to help remove same.

Coverage	:	N/A
Mixing Ratio	:	N/A
Thinner	:	Fresh water
Recoat	:	N/A
Curing Time	:	N/A
Aged Recoat	:	N/A
Finish	:	Water white

Health and Safety

Wear full acid protective gear including gloves and goggles. Use with adequate ventilation and do not use near naked flames.